

2011 Aerial Photo of Lake Red Rock Sediment Deposits at confluence of Des Moines River


(Yellow arrow in both photos points to sand pile from former sand quarry as visual reference to extent of sediment coverage.)

2021 Aerial Photo of Lake Red Rock Sediment Deposits at confluence of Des Moines River

Figure 3. Red Rock Sedimentation Aerial Photos from ISU GIS Website



Lake Red Rock Fish Habitat Enhancement Project



1996 Aerial Photo of Red Rock Lake Cove, Left side of photo is west, top is north



2011 Aerial Photo of Red Rock Lake Cove, Left side of photo is west, top is north

Figure 4. Lake Red Rock Shoreline Erosion



2002 Aerial Photo of Red Rock Lake Cove, Left side of photo is west, top is north



2016 Aerial Photo of Red Rock Lake Cove, Left side of photo is west, top is north

Photos from ISU GIS Website

Supporting Material



2008 Aerial Photo of Red Rock Lake Cove, Left side of photo is west, top is north




2016 Aerial Photo of Red Rock Lake Cove, Left side of photo is west, top is north

Lake Red Rock Fish Habitat Enhancement Project

Supporting Material

IOWA'S WATERSHED MANAGEMENT AUTHORITIES



- 3. Catfish Creek WMA
- 4. Clear Creek Watershed Coalition
- 5. East Nishnabotna Watershed Coalition
- 6. English River WMA
- 7. Fourmile Creek WMA

- 10. loway Creek WMA
- 11. Little Sioux Headwaters Coalition
- 12. Lower Cedar WMA
- 13. Maquoketa River WMA
- 14. Middle-South Raccoon WMA
- 17. North & Middle Rivers WMA
- 18. North Raccoon River Watershed Management Coalition
- 19. Shell Rock River Watershed Management Coalition
- 20. Soap Creek Watershed Board
- 21. South Central Iowa Cedar Creek WMA

- 23. Upper Cedar River WMA
- 24. Upper Iowa WMA
- 25. Upper Wapsipinicon River WMA
- 26. Walnut Creek WMA
- 27. West Nishnabotna Watershed Coalition




Figure 6. Funded Water Quality Initiatives